



100


COATO WORKSHOP, INC. ATTORNEY DOCKET NO. 021525-000200US



**FIRST GEAR 10
MPH**



**SECOND GEAR 20
MPH**



**THIRD GEAR 30
MPH**

**NTH GEAR MPH
OR KH**




FIG. 1

201507201.030102

COATO WORKSHOP, INC. ATTORNEY DOCKET NO. 021525-000200US




FIG. 2

20100201.030102

COATO WORKSHOP, INC. ATTORNEY DOCKET NO. 021525-000200US.




FIG. 3

10087201.030102
20100910

COATO WORKSHOP, INC. ATTORNEY DOCKET NO. 021525-000200US




FIG. 4

20100501 10087201 030102

COATO WORKSHOP, INC. ATTORNEY DOCKET NO. 021525-000200US

500




FIG. 5

10087201.030102

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☒ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.